

# Technical Memo



Responsive partner.  
Exceptional outcomes.

**To:** Geoff Strack, SKB Environmental, Inc.  
**From:** Dave Parenteau, PE (MN), Wenck Associates, Inc.  
**Date:** January 14, 2016  
**Subject:** Annual Inspection SKB Rosemount Industrial Waste Facility - Report of CCR Landfill Inspection  
Wenck Project # B3053-0032

I hereby certify that this engineering document was prepared by me or under my direct supervision and that I am a duly registered Professional Engineer under the laws of the State of Minnesota.

A handwritten signature in blue ink, appearing to read 'David M. Parenteau', is written over a horizontal line.

David M. Parenteau  
PE # 41243

Jan 14, 2016

## Purpose

This memorandum fulfills the requirements of 40 CFR § 257.84 Inspection Requirements for CCR Surface Landfills, Part b, regarding annual inspection by a qualified professional engineer.

## Background and Applicability

SKB Environmental, Inc. owns and operates the SKB Rosemount Industrial Waste Facility, an industrial waste disposal facility operating under MPCA Solid Waste Permit SW-383, originally issued in January of 1992.

The site is located on a 236 acre parcel in Sections 19, 20 and 25 of Township 115 North, Range 18 West, in the city of Rosemount Minnesota, which is in Dakota County. The site is located between Minnesota State Highway 55 and Dakota County Road 38. The attached Figure 1 presents an overview of the site.

There are 6 permitted disposal cells in the Landfill. Past operating records indicate that CCR Material is contained in Cells 2 and 3.


## CCR Landfill Inspection (40 CFR § 257.84)

On December 28, 2015, Dave Parenteau conducted the on-site inspection the CCR Landfill. During the inspection the following activities were performed.

- ▲ Available information regarding status and condition of the CCR unit, including, but not limited to, files available in the operating record were reviewed. Past inspection reports were reviewed on site, and SKB Environmental, Inc. provided copies of cell construction documentation reports for review in preparing this report.

- ▲ The documentation reviewed covered the following topics
  - CCR unit design and construction information required by § 257.73(c)(1);
  - Previous periodic structural stability assessments required under § 257.73(d); It should be noted that §257.74 does not apply as the site is not new, nor is it a lateral expansion of an existing impoundment/landfill, therefore this is not addressed.
  - The results of inspections by a qualified person (contained below);
  - Results of previous annual inspections);

In general, most landfill cell embankments were constructed using granular soils and placed as engineered fill, compacted to 95% of Standard Proctor Dry Density in lift thicknesses ranging from 8 inches to 12 inches. A typical perimeter section, taken from the Cell 3A Construction Documentation Report, prepared by Foth & Van Dyke in October, 2005 is shown below.



- ▲ A visual inspection of the CCR units to identify signs of distress or malfunction of the CCR unit and appurtenant structures; and

There were no observed signs of distress or malfunction on either the CCR Impoundment or the CCR Landfill and their corresponding appurtenant structures.

Photos taken during the inspection are provided in Attachment 1 and Figure 2 shows where the photos were taken.

### CCR Landfill Inspection Report

40 CFR § 257.84, Subpart b.2 requires the following topics in italics be addressed within this report. The requirements are shown in italics with the response immediately afterwards for each item.

- (i) *Any changes in geometry of the impounding structure since the previous annual inspection;*

There were no apparent changes from the geometry of the impoundment when compared to the permit drawings or the past construction documentation reports.

- (ii) *The approximate volume of CCR contained in the unit at the time of the inspection;*

The approximate volume of CCR material contained in the landfill at the time of the inspection is 455,000 cubic yards.

- (iii) *Any appearances of an actual or potential structural weakness of the CCR unit, in addition to any existing conditions that are disrupting or have the potential to disrupt the operation and safety of the CCR unit and appurtenant structures; and*

None of the following were observed that could indicate structural weakness;

- Signs of slumping or rotational movement.
- Lateral or vertical distortion of the embankment crest
- Seepage on the outboard slope;
- Burrowing activity of varmints;

- (iv) *Any other change(s) which may have affected the stability or operation of the impounding structure since the previous annual inspection.*

There were no changes noted that may could potentially affect the stability or operation of the impoundment. Observations were consistent with those noted in that report.

### **Notification Requirements**

SKB Environmental, Inc. will comply with the recordkeeping requirements specified in § 257.105(g), the notification requirements specified in § 257.106(g), and the internet requirements specified in § 257.107(g) by the January 18, 2016 deadline.

### **Conclusions and recommendations**

The soils used for embankment construction have been granular in nature, and not subject to consolidation or softening with moisture. The cells are lined with a geomembrane ensuring that there is no leachate seeping through the embankment from the waste material. The landfill embankment crests are wide in width, have slopes no steeper than 3H:1V, and are relatively short in height, ranging from zero to approximately 20 feet in height. The slopes are well vegetated and the site is well run and maintained.

40 CFR § 257.83, Subpart b.5 and 40 CFR § 257.84, Subpart b.5 each require that if a deficiency or release is identified during an inspection, the owner or operator must remedy the deficiency or release as soon as feasible and prepare documentation detailing the corrective measures taken.

There were no deficiencies or releases identified during the inspection that require remedy as soon as possible.

## Attachment 1

---

Photos


**Photos of Coal Ash Inspection  
SKB Industrial Waste Facility, Rosemount, MN  
December 28, 2015**




1. NW Outer Slope  
Bottom of Slope  
Facing NE



2. NW Outer Slope  
Middle of Slope  
Facing NE




3. NW Outer Slope  
Top of Slope  
Facing NE



4. NW Outer Slope  
Top of Slope  
Facing SW






5. NW Outer Slope  
Middle of Slope  
Facing SW



6. WSW Interior Slope  
Top of Slope  
Facing SE



7. WSW Interior Slope  
Middle of Slope  
Facing SE




8. WSW Interior Slope  
Bottom of Slope  
Facing SE






9. WSW Interior Slope  
Middle of Slope  
Facing NE




10. WSW Interior Slope  
Top of Slope  
Facing NW




11. WSW Interior Slope  
Middle of Slope  
Facing NW



12. WSW Interior Slope  
Middle of Slope  
Facing W



13. W Corner Outer Slope  
Top of Slope  
Facing SW




14. W Corner Outer Slope  
Middle of Slope  
Facing SW






15. W Corner Outer Slope  
Bottom of Slope  
Facing SW



16. W Corner Outer Slope  
Top of Slope  
Facing NE



17. W Corner Outer Slope  
Middle of Slope  
Facing NE




18. W Corner Outer Slope  
Bottom of Slope  
Facing NE






19. SW Outer Slope  
Top of Slope  
Facing SE




20. SW Outer Slope  
Middle of Slope  
Facing SE




21. SW Outer Slope  
Bottom of Slope  
Facing SE



22. SW Outer Slope  
Top of Slope  
Facing NW




23. SW Outer Slope  
Top of Slope  
Facing SE



24. SW Outer Slope  
Middle of Slope  
Facing NW






25. SW Outer Slope  
Middle of Slope  
Facing SE



26. SW Outer Slope  
Bottom of Slope  
Facing NW




27. SW Outer Slope  
Bottom of Slope  
Facing SE




28. SW Outer Slope  
Top of Slope  
Facing NW







29. SW Outer Slope  
Top of Slope  
Facing SE




30. SW Outer Slope  
Middle of Slope  
Facing NW




31. SW Outer Slope  
Middle of Slope  
Facing SE



32. SW Outer Slope  
Bottom of Slope  
Facing NW



33. SW Outer Slope  
Bottom of Slope  
Facing SE



34. SW Outer Slope  
Top of Slope  
Facing NW







35. SW Outer Slope  
Top of Slope  
Facing SE



36. SW Outer Slope  
Middle of Slope  
Facing NW



37. SW Outer Slope  
Middle of Slope  
Facing SE




38. SW Outer Slope  
Bottom of Slope  
Facing NW







39. SW Outer Slope  
Bottom of Slope  
Facing SE



40. S Corner Outer Slope  
Top of Slope  
Facing NW




41. S Corner Outer Slope  
Middle of Slope  
Facing NW



42. S Corner Outer Slope  
Bottom of Slope  
Facing NW



43. S Corner Outer Slope  
Top of Slope  
Facing NE




44. SE Outer Slope  
Top of Slope  
Facing SW







45. SE Outer Slope  
Top of Slope  
Facing NE



46. SE Outer Slope  
Top of Slope  
Facing SW



47. SE Outer Slope  
Top of Slope  
Facing NE




48. E Corner Outer Slope  
Top of Slope  
Facing SW






49. SE Outer Slope  
Top of Slope  
Facing NE




50. SE Outer Slope  
Top of Slope  
Facing SW



51. E Corner Outer Slope  
Top of Slope  
Facing NW



52. NE Outer Slope  
Top of Slope  
Facing SE




53. NE Outer Slope  
Top of Slope  
Facing NW



54. NE Outer Slope  
Top of Slope  
Facing SE






55. N Corner Outer Slope  
Top of Slope  
Facing SE



56. N Corner Outer Slope  
Top of Slope  
Facing SW






57. NW Outer Slope  
Bottom of Slope  
Facing NE



58. NW Outer Slope  
Bottom of Slope  
Facing SW





SKB Industrial Waste Facility  
Rosemount, MN

**Coal Ash Inspection**


**SKB Industrial Waste Facility, Rosemount, MN**



DEC 2015

Figure 1





**Photo Locations of Coal Ash Inspection**

**SKB Industrial Waste Facility, Rosemount, MN**



Responsive partner. Exceptional outcomes.

DEC 2015

Figure 2